


Addition masonry walls are complete



Beam bearing fix is complete



Main entry is open



Concrete sidewalks at townhomes



Continue new parking lot excavation



Remove patio by community room

