



Shower Demo	Kitchen wall cutout
 A photograph showing a bathroom during a shower area demolition. A toilet is visible on the left, and the shower pan and walls are being removed, leaving a rough, exposed structure.	 A photograph of a kitchen with wooden cabinets, a white refrigerator, a white stove, and a white countertop. A section of the wall above the countertop has been removed, creating an opening.
Shower drywall	Kitchen demo
 A photograph showing the shower area after the drywall has been installed. The walls are now a solid light green color, and a white sink and mirror are visible on the right side.	 A photograph showing the kitchen during a demolition phase. The floor is covered in debris, and the walls are partially removed, revealing the underlying structure.
Shower Panels and Pan	New Kitchen
 A photograph showing the shower area with new white panels and a white pan installed. The shower is now fully enclosed and ready for use.	 A photograph showing the completed kitchen. It features dark wood cabinets, a white refrigerator, a white stove, and a white countertop. The walls are a light beige color, and the floor is covered in light-colored tiles.